

GLOBAL Rotax MAX Challenge Technical Regulation 2022

Bulletin no.: 04

Valid as of: 2022 05 31

Addendum/changes (highlighted in yellow) to Global RMC Technical Regulation 2022, Edition 2021 10 12

6.6.2. Distance of exhaust valve flange at cylinder to piston

Turn crankshaft until the piston just closes the exhaust port. Insert the exhaust valve gauge (Rotax 277030) as shown in the picture until it stops at the flange.

At the contact area between exhaust valve gauge (Rotax 277030) and the flange of the cylinder, a feeler gauge 0,05 mm may not fit between the gauge and the flange.

The measurement must be performed outside the exhaust valve contact area indicated in red below.

